

Maintenance Report – West Avenue

1. The Sears Plot– Coping displaced by a tree, one coping slab broken in half.
2. Emma and Phila Johnson, Top half not safely balanced. One pillar is free standing and another is turned in the wrong direction. Small break on one pillar. Small repairs needed to the artwork and roses. **This stone is unstable and should be rebalanced as soon as possible as the marker is priceless.**
3. Mabel Heiner Armstead – Reset stone.
4. Rose-Burnett – Left marble vase stem is horizontally fractured.
5. Mittie Howard – Vase broken.
6. Alwilda Goodnight – Horizontal crack in tablet.
7. Armstead Hume – Stone sunk in mud.
8. Mrs. Eliza A. Williams – Stone next to it is broken and crumbled. Old stone is irreparable.
9. Martin H. Loftus – Tablet broken in half and lying on the ground. It was sunk in the mud so I pulled it out and we cleaned it. The horizontal break needs to be fixed and the stone reset.
10. W. H. and Mary Terry – Reset stone.
11. The Rufus Henderson Plot – Coping is displaced by a tree.
12. H. H. Bachelder – Pot broken off and missing.
13. Elizabeth and Geo Ewing – Marble slab is broken in half. Footstone to plot broken in half.
14. The Scholibo Plot – Top broken off of the smallest tablet marker in the plot. The broken piece is present, and can be easily reattached.
15. The Bond/Hanson Plot – Coping sinking in mud.
16. The Japhet Plot – Coping sinking in mud.
17. The Louise Howard and Lelia Bradford Plot – Marble coping slightly sunk in mud and slightly out of line in the back of the plot.
18. Mary Tharp – Reset Stone.
19. The Edna Merle Teague and P. Moore and Mrs. K. A. Moore Plot – coping displaced and sinking.
20. The Crawford Plot – Concrete coping badly broken and crumbled.
21. The Sharp Plot – Concrete bench cracked in half. I recommend some kind of support under the crack or it will most likely break again after it is repaired.
22. Nathaniels Brush – Stone needs to be buried
23. The Norrell Plot – One of the two large granite balls is missing.
24. Haskins – Top of footstep Broken.
25. Brick Wall – When you enter the cemetery, within the first 5 feet of the start of the brick for West Avenue, there is about 1-1.5 foot section that is broken and needs to be repaired.