



BAD ORDER

Car Init.	Car Number	Kind	Grde	Day	Time	Ripc	Location	Serial Number
Location (Circle)	"A" End	"B" End	- R or L	9024	1-16-77	Other Defects	Insp. Init.	
If defect due to accident give date occurred	Place of Accident	Company Responsible						

PSB X 25023

2 cast iron shoes

82-4

MAIN SHOP

9251
Lube 4-12-77

9111
Lube 4-11-77



BAD ORDER

Car Init.	Car Number	Kind	Grde	Day	Time	Ripc	Location	Serial Number
Location (Circle) "A" End "B" End - R or L						Other Defects <i>cast iron</i>		Insp. Init.
If defect due to accident give date occurred			Place of Accident <i>82 - L7</i>			Company Responsible		
1	* Air Brakes	11	* Brake, Hand	21	* Hand Holds	31	* Sill, Side	
2	* Angle Cock	12	Clearances	22	Journal Box	32	Sill Interm.	
3	* Air Hose	13	* Coupler, Defective	23	Journal Hot	33	* Sill Step	
4	Body Bolster	14	* Coupler Knuckle	24	Journal Box Repack	34	Side Bearings	
5	Bolster Truck	15	* Coupler Opp. Lever	25	Load Shifted	35	Stakes	
6	* Brake Beam	16	Coupler Carry Iron	26	* Ladders	36	Springs	
7	* Brake Hanger	17	Draft Gear	27	* Running Boards	37	Side Defective	
8	* Brake Pin	18	Doors	28	Roof	38	Side Truck Frame	
9	* Brake Rod	19	End Defective	29	Sill, Centre	39	Wheels	
10	* Brake Pipe	20	Floor Defective	30	Sill, End	40	Other Defects	