

# LANDMARKS

Dutchess County Landmarks Association, Inc.  
P. O. Box 944, Poughkeepsie, New York 12602

## BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP \_\_\_\_\_ Code \_\_\_\_\_  
or CITY \_\_\_\_\_ No. \_\_\_\_\_

1. BUILDING NAME Julia O'Neill

2. VILLAGE or HAMLET Cherry Street - Red Hook W

3. STREET or ROAD 11 Cherry Street

4. OWNERSHIP: Public \_\_\_\_\_ Private ☒

5a. PRESENT OWNER Julia O'Neill

Mailing Address Fraser Street  
Red Hook, New York

Deed Recorded: Liber \_\_\_\_\_ Page \_\_\_\_\_

5b. PRESENT OCCUPANT Rented Apts

Mailing Address \_\_\_\_\_

5c. FORMER OWNERS  
Name \_\_\_\_\_

Dates of Ownership \_\_\_\_\_

Deed Recorded  
Liber \_\_\_\_\_ Page \_\_\_\_\_

6. USES  
Present \_\_\_\_\_

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No \_\_\_\_\_  
Interior accessible: Explain Rented Apartments

8. BUILDING MATERIAL: clapboard ☒ stone ☒ brick \_\_\_\_\_  
board and batten \_\_\_\_\_ shingles \_\_\_\_\_ stucco \_\_\_\_\_ other \_\_\_\_\_

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) ☒  
b. wood frame with light members (balloon frame) \_\_\_\_\_ c. masonry load bearing walls \_\_\_\_\_  
d. metal (explain) \_\_\_\_\_ e. other \_\_\_\_\_

10. CONDITION: excellent \_\_\_\_\_ good ☒ fair \_\_\_\_\_ deteriorated \_\_\_\_\_

11. INTEGRITY: Original site ☒ If moved, when and from where \_\_\_\_\_  
List major alterations and dates: Sections added

12. ROOF: a. gable ☒ saltbox \_\_\_\_\_ gambrel \_\_\_\_\_ hip \_\_\_\_\_ mansard \_\_\_\_\_ other \_\_\_\_\_ dormers \_\_\_\_\_  
b. wood shingles ☒ asphalt shingles \_\_\_\_\_ slate \_\_\_\_\_ metal \_\_\_\_\_ other \_\_\_\_\_

14. THREATS TO BUILDING: none known ☒ zoning \_\_\_\_\_ roads \_\_\_\_\_ developers \_\_\_\_\_ deterioration \_\_\_\_\_  
other \_\_\_\_\_

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 1/2 Acre acreage \_\_\_\_\_ barn \_\_\_\_\_  
carriage house \_\_\_\_\_ garage \_\_\_\_\_ privy \_\_\_\_\_ shed \_\_\_\_\_ greenhouse \_\_\_\_\_ shop \_\_\_\_\_ gardens \_\_\_\_\_  
landscape features \_\_\_\_\_ other \_\_\_\_\_

16. SURROUNDINGS OF BUILDING: open land \_\_\_\_\_ woodland \_\_\_\_\_ scattered buildings \_\_\_\_\_ residential ☒  
densely built-up \_\_\_\_\_ commercial \_\_\_\_\_ industrial \_\_\_\_\_ other \_\_\_\_\_

### 13. MAP

North





17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. \_\_\_\_\_

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

Lower level of house made of 24 inch stone wall -  
3rd story added at later date -

19. INITIAL CONSTRUCTION:

Date About 1840 Architect \_\_\_\_\_ Builder \_\_\_\_\_

SIGNIFICANT ALTERATIONS:

Date \_\_\_\_\_ Architect \_\_\_\_\_ Builder \_\_\_\_\_

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary \_\_\_\_\_ Federal \_\_\_\_\_ Greek Revival \_\_\_\_\_ Victorian \_\_\_\_\_ Other \_\_\_\_\_

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. \_\_\_\_\_ 1858 Dutchess Co. \_\_\_\_\_

1867 Atlas \_\_\_\_\_ School District No. \_\_\_\_\_

1876 Atlas \_\_\_\_\_ School District No. \_\_\_\_\_

Location of  
early photographs: \_\_\_\_\_

Inventory by Mrs. Lloyd Hapeman

Address 11 Park Ave

Red Hook, NY

Date 5/5/75

Tel. 758-1551



# BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

## FOR OFFICE USE ONLY

UNIQUE SITE NO. \_\_\_\_\_  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

YOUR NAME: Mrs. Lloyd Hageman DATE: 4/30/75

YOUR ADDRESS: 11 Park Ave Red Hook TELEPHONE: 758-1551

ORGANIZATION (if any): LANDMARKS

\*\*\*\*\*

### IDENTIFICATION


1. BUILDING NAME(S): Julia O'Neill  
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook  
3. STREET LOCATION: 11 Cherry St  
4. OWNERSHIP: a. public ☐ b. private ☒  
5. PRESENT OWNER: Julia O'Neill ADDRESS: Franklin St. Red Hook  
6. USE: Original: home Present: rented - residential  
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐  
Interior accessible: Explain rented

### DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☒ c. brick ☐ d. board and batten ☐  
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: \_\_\_\_\_  
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☒  
(if known) b. wood frame with light members ☐  
c. masonry load bearing walls ☐  
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_  
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐  
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? \_\_\_\_\_  
c. list major alterations and dates (if known): Sections added

12. PHOTO:

13. MAP:





14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐  
d. developers ☐ e. deterioration ☐  
f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY:  
a. barn ☐ b. carriage house ☐ c. garage ☐  
d. privy ☐ e. shed ☐ f. greenhouse ☐  
g. shop ☐ h. gardens ☐  
i. landscape features: \_\_\_\_\_  
j. other: \_\_\_\_\_
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
a. open land ☐ b. woodland ☐  
c. scattered buildings ☐  
d. densely built-up ☐ e. commercial ☐  
f. industrial ☐ g. residential ☒  
h. other: \_\_\_\_\_
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: About 1840

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

*Lower level of house made of 24 inch  
stone wall -*

*3rd story added later on*

21. SOURCES:

*Mrs. Julia O'Neill*

22. THEME: