

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook N.Y. Code No. _____

1. BUILDING NAME Mrs. Ed. Baden - (E. Bradley) ^{owned by}

2. VILLAGE or HAMLET Red Hook, N.Y.

3. STREET or ROAD 22 St. John's St.

4. OWNERSHIP: Public _____ Private ☒

5a. PRESENT OWNER Mrs. Eugenia Bradley

Mailing Address Red Hook.

Deed Recorded: Liber _____ Page _____

5b. PRESENT OCCUPANT Mr. & Mrs. Ed. Baden

Mailing Address 22 St. John's St.
Red Hook, N.Y.

5c. FORMER OWNERS Name _____ Dates of Ownership _____

Bradley 1954 - Norton 8-40 1954

Present owner E. Bradley 67

Deed Recorded Liber _____ Page _____

6. USES Present _____

home

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No _____
Interior accessible: Explain by appt

8. BUILDING MATERIAL: clapboard ☒ covered with Alum. siding ☒
board and batten _____ shingles _____ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) ☒ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good ☒ fair _____ deteriorated _____

11. INTEGRITY: Original site yes If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable _____ saltbox _____ gambrel _____ hip _____ mansard _____ other regular dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal _____ other _____


14. THREATS TO BUILDING: none known ☒ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 1/4 A. acreage _____ barn _____
carriage house _____ garage ☒ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features good planting other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings ☒ residential _____
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date late 1800's Architect probably 1870 Builder Gedney

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian ☒ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

*This house was a part of the Sedney Estate.
Sedney built several houses in this area.*

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

all supplied info. came from the old deeds.

Location of
early photographs: _____

Inventory by Keith Tucker

Address 200 Turkey Hill Rd -
Red Hook

Date 7-15-75
Tel. 914-758-8339

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Ruth H. Archer DATE: 5-25-75

YOUR ADDRESS: 200 Turney Hill Rd TELEPHONE: 758-8339

Red Hook, N.Y. 12571
ORGANIZATION (if any): _____

IDENTIFICATION


1. BUILDING NAME(S): Mrs. Edward Baden (Bradley)
2. COUNTY: _____ TOWN/CITY: _____ VILLAGE: _____
3. STREET LOCATION: 22 St. John
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Eugenia Bradley ADDRESS: Red Hook
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: cou. alum. siding
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐
(if known) b. wood frame with light members ☒
c. masonry load bearing walls ☐ field stone
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

Part of Kedney Estate, Gedney was builder

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):
Most attractive small colonial.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: in late 1800's
ARCHITECT: none
BUILDER: Gedney
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

Mrs. Eugenia Bradley, present owner

22. THEME: