

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP _____ Code
or CITY _____ No. _____

1. BUILDING NAME Maple Grove

2. VILLAGE or HAMLET _____

3. STREET or ROAD Linden Ave Ext.

4. OWNERSHIP: Public _____ Private ☒

5a. PRESENT OWNER Mr. + Mrs. C. H. Baxter

Mailing Address Box 27 - Rt 1
Red Hook, N.Y. 12571

Deed Recorded: Liber 637 Page 11

5b. PRESENT OCCUPANT Mr. + Mrs. C. H. Baxter

Mailing Address Box 27 - Rt 1
Red Hook, N.Y. 12571

5c. FORMER OWNERS

Name	Dates of Ownership
<u>Cornelius Elmendorf. Thomas Elmendorf.</u>	
<u>Mary Elmendorf Potts</u>	
<u>Eugene + Mima Budd</u>	
<u>Eugene Budd + Mary Hardin</u>	

Deed Recorded
Liber _____ Page _____

6. USES Farm
Present _____

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard _____ stone _____ brick ☒
board and batten _____ shingles ☒ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent ☒ good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site ☒ If moved, when and from where _____
List major alterations and dates:
Originally a story + a half - basement but then

12. ROOF: a. gable ☒ saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles ☒ slate ☒ metal _____ other _____


14. THREATS TO BUILDING: none known _____ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 2 acres acreage 250 barn ☒
carriage house ☒ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land ☒ woodland _____ scattered buildings _____ residential ☒
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

Outside walls - some brick + plaster

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

~~Pre~~-Revolutionary ☒ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas ☒ _____ School District No. 1

1876 Atlas _____ School District No. _____

Location of
early photographs: _____

Inventory by

Mary B. Hardin

Address

Box 26 - Rt 1

Red Hook, N.Y. 12571

Date

May 15, 1975

Tel.

758-0937

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Mary B. Hardin DATE: May 15, 1975
YOUR ADDRESS: Box 26 - Rt 1 TELEPHONE: 758-1937
Red Hook, N.Y.
ORGANIZATION (if any): _____

IDENTIFICATION

1. BUILDING NAME(S): Maple Grove
2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: Red Hook
3. STREET LOCATION: Studen Ave Ext.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. C.H. Bayler ADDRESS: Box 27 Rt 1, Red Hook, N.Y.
6. USE: Original: Dwelling Present: Dwelling
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain Private Dwelling

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☒ d. board and batten ☐
e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐
(if known) b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

First a story and a half, then made into a two story house

12. PHOTO:

13. MAP:

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☒ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
- ARCHITECT: _____
- BUILDER: _____
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
21. SOURCES:
22. THEME: