

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY RED Hook Code No. _____

1. BUILDING NAME _____
2. VILLAGE or HAMLET RED Hook
3. STREET or ROAD WEST MARKET ST.
4. OWNERSHIP: Public _____ Private X
- 5a. PRESENT OWNER ELIZABETH WACKER
46 WEST MARKET ST.
Mailing Address RED Hook, N.Y.
- Deed Recorded: Liber _____ Page _____
- 5b. PRESENT OCCUPANT 2 APTS.
- Mailing Address _____

5c. FORMER OWNERS

Name	Dates of Ownership
<u>SUSANNA GEDNEY</u>	<u>1890's</u>
<u>GORDON VOORHIS</u>	<u>1940's</u>
<u>ELIZABETH WACKER</u>	<u>1973-</u>

Deed Recorded
Liber _____ Page _____

6. USES

Present 2 family house
BLACK SMITH Shop
Private House

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard originally stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other alum siding

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) X
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent X good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site X If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable X saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal _____ other _____

14. THREATS TO BUILDING: none known X zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot _____ acreage 1/4 barn _____
carriage house _____ garage X privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential X
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP


North

W

WEST MARKET ST.

RT. 199 WEST

South



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

*House made into 2-6 room apts so
nothing of original structure is there.*

19. INITIAL CONSTRUCTION:

Date 1890's Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of
early photographs: _____

Inventory by

EUGENIA R. BRADLEY

Address

R.D. 2 Box 405
RED HOOK, NY 12571

Date

6/75

Tel.

914-758-4351

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: BRADLEY, EUGENIA R. DATE: 6/75

YOUR ADDRESS: RD 2, Box 405, RED Hook TELEPHONE: 914-758-4351

ORGANIZATION (if any): LAND MARKS

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: RED Hook
3. STREET LOCATION: 46 W. MARKET ST.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: WACKER, ELIZABETH ADDRESS: 46 W. MARKET ST.
6. USE: Original: BLACKSMITH SHOP Present: 2 APTS.
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐


Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ ^{originally} b. stone ☐ c. brick ☒ ^{Now} d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Alum. Siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:

- a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: acresage 74

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):

- a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

*House made into 2 (6 room apts) so
nothing of original structure is there*

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1890's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: