LANDMARKS Dutchess County Landmarks Association, Inc. P.O. Box 944, Poughkeepsie, New York 12602

TOW or CI	BUILDING - STRUCTURE INVENTORY FORM NSHIP Code No
•	BUILDING NAME
2.	VILLAGE Red Hook
3.	STREET 53 Garden Street
4. 5a.	OWNERSHIP: Public Private X PRESENT G. Christina Shook Mailing Standen Street Address Red Hook N. V. 12571 Deed Recorded: Liber 1257 Page 987
5b.	PRESENT Same Mailing Address
	FORMER OWNERS Name Comparison of Deed Recorded Liber Page Comparison of Deed Record
	No. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No.
	Interior accessible: Explain
	STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) b. wood frame with light members (balloon frame) c. masonry load bearing walls d. metal (explain) e. other
10.	CONDITION: excellent good X fair deteriorated deteriorated
11.	INTEGRITY: Original site If moved, when and from where List major alterations and dates: About 1930, Kitchen was made into dining room and a part of the porch was made into the Kotchen.
12.	ROOF: a. gable X saltbox gambrel hip mansard other dormers b. wood shingles slate metal other other
	THREATS TO BUILDING: none known zoning roads developers deterioration
15.	RELATED OUTBUILDINGS AND PROPERTY: size of lot acreage barn carriage house garage privy shed greenhouse shop gardens other
16.	SURROUNDINGS OF BUILDING: open land woodland scattered buildings residential densely built-up commercial industrial other
	(over)

13. MAP

North

8.	other notable features of Spiral file double	F THE BUILDING AND SITE: bey window from	(Include interior features if known) Loundation to roof.
) .	INITIAL CONSTRUCTION:	,	
•	Date		
	SIGNIFICANT ALTERATIONS: Date	Architect	Builder
).	ARCHITECTURE: (Indicate period Pre-Revolutionary Feder	or style if known) ral Greek Revival	Victorian Other
	HISTORICAL INFORMATION AND When The house was oron the construction	DE TRADITIONS: being built a co	indstorm come and blicad would not live The
· Q. A. O. F	HISTORICAL INFORMATION AND When The house was own the construction ecame of this, Fe rould be anchered rateigh land About 1930, The 10 and of the porch was	DERADITIONS: being built a wo made medo Luit in rods. with iron rods. wheher we made medo Luite Ne 1	indstorm Come and blicad world not live The snow reed that the horn this was originally Peter into The dening room and Cetchen.
)	SOURCES: Maps: (List name of owner as sha 1850 Dutchess Co	own on map and School District 1858 Dute S	inte he Clining Room and Cetchen.
)	SOURCES: Maps: (List name of owner as sha 1850 Dutchess Co	own on map and School District 1858 Dute S	where applicable) thess Co chool District No

BUILDING-STRUCTURE INVENTORY FORM	FOR OFFICE USE ONLY				
DIVISION FOR HISTORIC PRESERVATION	UNIQUE SITE NO				
NEW YORK STATE PARKS AND RECREATION	SERIES				
ALBANY, NEW YORK (518) 474-0479	NEG. NO.				
YOUR NAME: NOSemany E. COONS	DATE: May 3, 1973				
YOUR NAME: Rosemany E. Coons DATE: May 3, 1975 YOUR ADDRESS: 34 Garden St., Red Hook TELEPHONE: 914-758-6334					
ORGANIZATION (if any):					
* * * * * * * * * * * * * * * * * * *	DDRESS: 53 Gardon St. Red Hook				
7. ACCESSIBILITY TO PUBLIC: Exterior visible from	n public road: Yes 🔼 No 🗆				
DESCRIPTION Interior accessible:	Explain				
8. BUILDING a. clapboard b. stone c. cobblestone f. shingles					
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking in the state of the system in the sys	ers				
10. CONDITION: a. excellent □ b. good ☒ c. 11. INTEGRITY: a. original site ☒ b. moved □ c. list major alterations and dates (if k About 1930 K. tehen was mad porch was made nato the Katchen.	if so.when?				
12. PHOTO:	3. MAP:				
	od o				
	Ph. 11. 100				
	53				
	GARDEN ST				

14.	THREATS TO BUILDING: a. none known b. zoning c. roads e. deterioration e. deterioration	
15.	f. other:	
16.	SURROUNDINGS OF THE BUILDING (check more than one if necessary): a. open land b. woodland c. scattered buildings d. densely built-up e. commercial f. industrial g. residential h. other:	
17.	INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS: (Indicate if building or structure is in an historic district)	
18.	OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known): Spiral-like double bay window from foundation	to roof.
<u>SIG</u> 19.	NIFICANCE DATE OF INITIAL CONSTRUCTION: 1909	
	ARCHITECT:	
	BUILDER: Norman + William Mead	
don beco be	HISTORICAL AND ARCHITECTURAL IMPORTANCE: When the house was being built, a windstorm came on the construction. Mrs. Gertrude mead would not like and of this until she was convinced that the house was anchored with iron rods. This was originally Peter	oould
tro	aleigh land.	
	aleigh land.	
	sources:	