

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook Code No. _____

1. BUILDING NAME Stelman residence

2. VILLAGE or HAMLET Red Hook

3. STREET or ROAD 54 North Broadway

4. OWNERSHIP: Public _____ Private ☒

5a. PRESENT OWNER Dr. & Mrs Carl Stelman

Mailing Address 54 N. Biway
Red Hook, N.Y. 12571

5b. PRESENT OCCUPANT Dr. & Mrs Carl Stelman

Mailing Address 54 N. Biway
Red Hook, N.Y. 12571

5c. FORMER OWNERS

| Name | Dates of Ownership | Deed Recorded Liber | Page | 6. USES Present |
|-------------------|--------------------|---------------------|-------|-----------------|
| <u>Dr. Cotter</u> | _____ | _____ | _____ | <u>Home</u> |
| <u>Griffing</u> | _____ | _____ | _____ | <u>+ office</u> |
| <u>Leon</u> | _____ | _____ | _____ | _____ |
| <u>Hevenor</u> | _____ | _____ | _____ | _____ |

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No _____
Interior accessible: Explain No

8. BUILDING MATERIAL: clapboard ☒ stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) ☒ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent ☒ good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site ☒ If moved, when and from where _____
List major alterations and dates: None

12. ROOF: a. gable _____ saltbox _____ gambrel _____ hip _____ mansard ☒ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate ☒ metal _____ other _____

14. THREATS TO BUILDING: none known ☒ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 1 1/4 acres acreage _____ barn ☒
carriage house _____ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential ☒
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

High ceilings, plaster arches, carved moldings, curved staircase, slate fireplaces (2), back staircase, wrought iron railing surrounding French mansard roof, cupola, tombstone of original owner

19. INITIAL CONSTRUCTION:

Date 1874 Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian ☒ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas B School District No. _____

1876 Atlas R. B. Herenon School District No. _____

Location of early photographs: _____

Inventory by _____

Address _____

Date _____

Tel. _____

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Dr. & Mrs. Carl Stelman DATE: 2/23/76

YOUR ADDRESS: 34 N. B'way, Red Hook TELEPHONE: 758-0455

ORGANIZATION (if any): _____

IDENTIFICATION

1. BUILDING NAME(S): None
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: 34 N. B'way, Red Hook, N.Y. 12571
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Dr. Carl Stelman ADDRESS: 34 N. B'way
6. USE: Original: private home Present: home-office
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain No

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐
b. wood frame with light members ☒
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

High ceilings, plaster arches, carved moldings,
curved staircase, slate fireplaces (2), back staircase,
wrought iron railing surrounding roof (French mansard
with slate), cupola; tombstone of original owner

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1874(?)

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: Victorian architecture

21. SOURCES:

Mrs. Carl F. Stelman