

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook Code No. _____

1. BUILDING NAME _____

2. VILLAGE or HAMLET Red Hook

3. STREET or ROAD 21 Fisk

4. OWNERSHIP: Public _____ Private

5a. PRESENT OWNER Rudy John ELEANOR KNAUSS

Mailing Address Red Hook, NY

Deed Recorded: Liber _____ Page _____

5b. PRESENT OCCUPANT empty

Mailing Address _____

5c. FORMER OWNERS Name	Dates of Ownership	Deed Recorded Liber	Deed Recorded Page
<u>Knauss - Carol Lenal(?)</u>			
<u>Harace Louise Hoffman</u>	<u>4/11/1887</u>	<u>230</u>	<u>266</u>
<u>Jas. B Fisk</u>			

6. USES Present Residence

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam)
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good _____ fair deteriorated _____

11. INTEGRITY: Original site If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable _____ saltbox _____ gambrel _____ hip mansard _____ other _____ dormers _____
b. wood shingles asphalt shingles _____ slate metal _____ other French roof


14. THREATS TO BUILDING: none known _____ zoning _____ roads _____ developers _____ deterioration
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot _____ acreage barn _____
carriage house _____ garage privy shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land woodland _____ scattered buildings _____ residential
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

A large "wealthy" home among small work man's homes.

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

This house is older than 4/1887 but I was not able to go back farther in the deeds.

Size approx. 42 x 32' 3 full stories & basement

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

② 1867 Atlas Dutch Co - Red Hook School District No. _____

① 1876 Atlas Dutch Co - Red Hook School District No. _____

① Shows house, sm barn, lg barn across Fisk St

① Shows house & lg barn

F. Robbitt - VIG CLERK R.H. Biers ATLAS

both maps in County Record Dept.

Location of early photographs: _____

Inventory by Barbara C. Streib

Address 24 FISK ST

RED HOOK, N.Y.

Date May 1975

Tel. 914-878-8651

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Barbara C Strain DATE: May 1975
YOUR ADDRESS: 24 FISK ST TELEPHONE: 914-78-8671
ORGANIZATION (if any): Dutch Landmarkes Assoc Inc

IDENTIFICATION


- 1. BUILDING NAME(S): _____
- 2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
- 3. STREET LOCATION: 24 FISK
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: Rudy + Eleanor Knouss ADDRESS: Red Hook, NY
- 6. USE: Original: _____ Present: _____
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain _____

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
 d. developers e. deterioration
 f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
 a. barn b. carriage house c. garage
 d. privy e. shed f. greenhouse
 g. shop h. gardens
 i. landscape features: _____
 j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
 a. open land b. woodland
 c. scattered buildings
 d. densely built-up e. commercial
 f. industrial g. residential
 h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
 (Indicate if building or structure is in an historic district)

*a large "wealthy" home
 among small workman's houses*

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

*this house is older than 4/1887
 but I was not able to go back
 further in the deeds*

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
- ARCHITECT: _____
- BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

*House and barn across street
 appear on the 1867 Dutchess
 County Atlas for Red Hook*

21. SOURCES: *Dutchess Co - Red Hook 1867 Atlas*
 " " " " *1876 Atlas*

22. THEME: