

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP _____ Code No. _____
or CITY _____

1. BUILDING NAME "Old Blacksmith Shop"

2. VILLAGE or HAMLET Red Hook, N.Y.

3. STREET or ROAD Church St

4. OWNERSHIP: Public _____ Private

5a. PRESENT OWNER Mr. Miner Great

Mailing Address 19 Prince St
Red Hook, N.Y.

Deed Recorded: Liber _____ Page _____

5b. PRESENT OCCUPANT None

Mailing Address Church St

5c. FORMER OWNERS

Name	Dates of Ownership	Deed Recorded Liber	Deed Recorded Page
<u>Ms. Josephine Hard</u>	_____	_____	_____
<u>Mr. Chalow Becker</u>	_____	_____	_____
<u>George Storme</u>	_____	_____	_____

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No _____
Interior accessible: Explain Private

8. BUILDING MATERIAL: clapboard stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam)
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good _____ fair deteriorated _____

11. INTEGRITY: Original site If moved, when and from where _____

List major alterations and dates:
Originally 1 Big room In 1940 made into 2 smaller Rooms

12. ROOF: a. gable saltbox _____ gambrel _____ hip _____ mansard _____ other dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal _____ other _____


14. THREATS TO BUILDING: none known _____ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 50-65' acreage _____ barn _____
carriage house _____ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

Mr Treat has renovated interior & painted outside. Building is thought to be an old Blacksmith Shop originally. Mr Treat bought it around 1955.

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas (Probably) _____ School District No. _____

Location of early photographs: _____

Inventory by Edythe C. Budd
Address PO B 143
Red Hook, N.Y.

Date May 19
Tel. PL 8-8098

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY
UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Edythe C. Budd DATE: May 19, 1975
YOUR ADDRESS: POB. 143 Red Hook N.Y. TELEPHONE: PL 8-8090
ORGANIZATION (if any): _____

IDENTIFICATION


- 1. BUILDING NAME(S): "Old Blacksmith Shop"
- 2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: Red Hook
- 3. STREET LOCATION: Church St
- 4. OWNERSHIP: a. public b. private
- 5. PRESENT OWNER: Mr. Mener Great ADDRESS: Prince St
- 6. USE: Original: Blacksmith Shop Present: Private
- 7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes No
Interior accessible: Explain Private

DESCRIPTION

- 8. BUILDING MATERIAL: a. clapboard b. stone c. brick d. board and batten
e. cobblestone f. shingles g. stucco other: _____
- 9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints
b. wood frame with light members
c. masonry load bearing walls
d. metal (explain) _____
e. other _____
- 10. CONDITION: a. excellent b. good c. fair d. deteriorated
- 11. INTEGRITY: a. original site b. moved if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known b. zoning c. roads
d. developers e. deterioration
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn b. carriage house c. garage
d. privy e. shed f. greenhouse
g. shop h. gardens
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land b. woodland
c. scattered buildings
d. densely built-up e. commercial
f. industrial g. residential
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
21. SOURCES:
22. THEME: