

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP _____ Code
or CITY _____ No. _____

1. BUILDING
NAME _____

2. VILLAGE
or HAMLET Red Hook

3. STREET
or ROAD Garden Street

4. OWNERSHIP: Public _____ Private X

5a. PRESENT
OWNER Beatrice Hyde

Mailing
Address 41 Garden Street
Red Hook, N.Y. 12571

Deed Recorded: Liber _____ Page _____

5b. PRESENT
OCCUPANT Beatrice Hyde

Mailing
Address _____

5c. FORMER OWNERS
Name _____

Dates of
Ownership _____

Deed Recorded
Liber _____ Page _____

6. USES
Present Residence

John Ham

Residence

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard _____ stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other alum. siding

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent X good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site _____ If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable X saltbox _____ gambrel X hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal _____ other _____


14. THREATS TO BUILDING: none known X zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot _____ acreage _____ barn _____
carriage house _____ garage X privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other "Stoke house" + Pheasant House

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential X
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

This is another example of a garage made from the end of a greenhouse. The stone house sits on its original site and the greenhouse extended south from it.

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

Porch on the house runs along the entire south + east sides.
Brick forming garden path to from Cruger's Island.

19. INITIAL CONSTRUCTION:

Date 1867 to 1876 Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

Miss Hyde used to bunch violets in the greenhouse when she was a young girl.

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas P.G. Fraleigh School District No. _____

1891 Map - L.B. Curtis

Location of early photographs: _____

Inventory by Rosemary E. Coore

Address 34 Garden St.

Red Hook, NY 12571

Date May 3, 1975

Tel. 914-758-6334

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Rosemary E. Coons DATE: May 3, 1975

YOUR ADDRESS: 34 Garden St, Red Hook TELEPHONE: (914) 758-6334

ORGANIZATION (if any): _____

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: Red Hook
3. STREET LOCATION: 41 Garden Street
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Beatrice Hyde ADDRESS: 41 Garden Street
6. USE: Original: Residence Present: Residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: alum. siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☐ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:

- a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: "Stoke House" & Pheasant House

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):

- a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Here is another example on this street of a garage made from the end of a greenhouse. The stoke house sits on its original site and the greenhouse extended south from it.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

The Porch on this house runs along the entire south & east sides. Brick forming the garden path is from historic Cruger's Island

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1867 to 1876

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

Present owner used to bunch violets in the greenhouse when she was a young girl.

21. SOURCES: 1876 Atlas
1891 map

22. THEME: