

LANDMARKS

Dutchess County Landmarks Association, Inc.
P.O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY RED HOOK Code No. _____

1. BUILDING NAME _____

2. VILLAGE or HAMLET RED HOOK

3. STREET or ROAD WEST MARKET ST.

4. OWNERSHIP: Public _____ Private X

5a. PRESENT OWNER DONALD E. NORTON

Mailing Address 15 WEST MARKET
RED HOOK, N.Y.

8/23/40 Deed Recorded: Liber 584 Page 330

5b. PRESENT OCCUPANT WILLIAM BAXTER

Mailing Address 39 WEST MARKET
RED HOOK, N.Y. 12571

5c. FORMER OWNERS Name

Dates of Ownership

Deed Recorded Liber Page

6. USES PRIVATE HOME
Present Blacksmith Shop

SUSAN GEDNEY
DONALD E. NORTON

1890'S TO 1946
8/23/40 - '75 584 330

Private home

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard (originally) stone _____ brick now
board and batten _____ shingles _____ stucco _____ other alum siding

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls X
d. metal (explain) _____ e. other _____

10. CONDITION: excellent X good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site X If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable _____ saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal X other _____


14. THREATS TO BUILDING: none known X zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot _____ acreage _____ barn _____
carriage house _____ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential X
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. **INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:**

If structure is in an historic district, name district. _____

18. **OTHER NOTABLE FEATURES OF THE BUILDING AND SITE:** (Include interior features if known)

19. **INITIAL CONSTRUCTION:**

Date 1890's Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. **ARCHITECTURE:** (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian X Other _____

20a. **HISTORICAL INFORMATION AND TRADITIONS:**

21. **SOURCES:**

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of
early photographs: _____

Inventory by

Address

EUGENIA R. BRADLEY
RD 2, Box 405
RED Hook, N.Y. 12571

Date

Tel.

6/75
914-758-4351

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: EUGENIA R. BRADLEY DATE: 6/75

YOUR ADDRESS: R.D. 2, Box 405
RED HOOK, N.Y. TELEPHONE: 12571

ORGANIZATION (if any): _____

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: 39 WEST MARKET ST, Red Hook
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: DONALD E. NORTON ADDRESS: 15 WEST MARKET ST, Red Hook
6. USE: Original: Home Present: Home
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL:
a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: now aluminum siding
9. STRUCTURAL SYSTEM:
(if known)
a. wood frame with interlocking joints ☐
b. wood frame with light members ☐
c. masonry load bearing walls ☒
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known):
none

12. PHOTO: _____

13. MAP: _____



14. THREATS TO BUILDING: a. none known ☐ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☐
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1890'S
- ARCHITECT: _____
- BUILDER: B. GEDNEY
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME: