

# LANDMARKS

Dutchess County Landmarks Association, Inc.  
P.O. Box 944, Poughkeepsie, New York 12602

## BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY RED HOOK Code No. \_\_\_\_\_

1. BUILDING NAME \_\_\_\_\_

2. VILLAGE or HAMLET RED HOOK

3. STREET or ROAD WEST MARKET ST.

4. OWNERSHIP: Public \_\_\_\_\_ Private X  
5a. PRESENT OWNER DONALD E. NORTON

Mailing Address 14 THOMPSON ST.  
RED HOOK N.Y.

8/22/40 - Deed Recorded: Liber 584 Page 330  
5b. PRESENT OCCUPANT 4 APTS.

Mailing Address \_\_\_\_\_

5c. FORMER OWNERS  
Name

Dates of Ownership

Deed Recorded  
Liber Page

6. USES  
Present

SUSANNA GEDNEY

1880's-1940

\_\_\_\_\_

4 Apt. House  
HARDWARE STORE

DONALD E. NORTON

1940 -

584 330

+ then to 2 family house

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No \_\_\_\_\_  
Interior accessible: Explain \_\_\_\_\_

8. BUILDING MATERIAL: clapboard \_\_\_\_\_ stone \_\_\_\_\_ brick X  
board and batten \_\_\_\_\_ shingles \_\_\_\_\_ stucco \_\_\_\_\_ other \_\_\_\_\_

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) \_\_\_\_\_  
b. wood frame with light members (balloon frame) \_\_\_\_\_ c. masonry load bearing walls X  
d. metal (explain) \_\_\_\_\_ e. other \_\_\_\_\_

10. CONDITION: excellent X good \_\_\_\_\_ fair \_\_\_\_\_ deteriorated \_\_\_\_\_

11. INTEGRITY: Original site X If moved, when and from where \_\_\_\_\_  
List major alterations and dates:

Made into apartments in 1940

12. ROOF: a. gable \_\_\_\_\_ saltbox \_\_\_\_\_ gambrel \_\_\_\_\_ hip \_\_\_\_\_ mansard \_\_\_\_\_ other \_\_\_\_\_ dormers \_\_\_\_\_  
b. wood shingles \_\_\_\_\_ asphalt shingles \_\_\_\_\_ slate \_\_\_\_\_ metal \_\_\_\_\_ other \_\_\_\_\_

14. THREATS TO BUILDING: none known \_\_\_\_\_ zoning \_\_\_\_\_ roads \_\_\_\_\_ developers \_\_\_\_\_ deterioration \_\_\_\_\_  
other \_\_\_\_\_

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot \_\_\_\_\_ acreage \_\_\_\_\_ barn \_\_\_\_\_  
carriage house \_\_\_\_\_ garage \_\_\_\_\_ privy \_\_\_\_\_ shed \_\_\_\_\_ greenhouse \_\_\_\_\_ shop \_\_\_\_\_ gardens \_\_\_\_\_  
landscape features \_\_\_\_\_ other \_\_\_\_\_

16. SURROUNDINGS OF BUILDING: open land \_\_\_\_\_ woodland \_\_\_\_\_ scattered buildings \_\_\_\_\_ residential X  
densely built-up \_\_\_\_\_ commercial \_\_\_\_\_ industrial \_\_\_\_\_ other \_\_\_\_\_

13. MAP

North

W

WEST MARKET ST.

S

ST. JOHN ST  
Norton  
RT 9



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. \_\_\_\_\_

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

*Carved exterior trim.*

19. INITIAL CONSTRUCTION:

Date 1890's Architect \_\_\_\_\_ Builder \_\_\_\_\_

SIGNIFICANT ALTERATIONS:

Date \_\_\_\_\_ Architect \_\_\_\_\_ Builder \_\_\_\_\_

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary \_\_\_\_\_ Federal \_\_\_\_\_ Greek Revival \_\_\_\_\_ Victorian \_\_\_\_\_ Other \_\_\_\_\_

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. \_\_\_\_\_ 1858 Dutchess Co. \_\_\_\_\_

1867 Atlas \_\_\_\_\_ School District No. \_\_\_\_\_

1876 Atlas \_\_\_\_\_ School District No. \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Location of early photographs: \_\_\_\_\_

Inventory by  
Address

*EUGENIA R. BRADLEY*  
*R. 2, Box 405*  
*RED HOOK, N.Y. 12571*

Date  
Tel.

*6/75*  
*914-758-4351*



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐  
d. developers ☐ e. deterioration ☐  
f. other: \_\_\_\_\_
15. RELATED OUTBUILDINGS AND PROPERTY:  
a. barn ☐ b. carriage house ☐ c. garage ☐  
d. privy ☐ e. shed ☐ f. greenhouse ☐  
g. shop ☐ h. gardens ☐  
i. landscape features: \_\_\_\_\_  
j. other: none
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):  
a. open land ☐ b. woodland ☐  
c. scattered buildings ☐  
d. densely built-up ☐ e. commercial ☐  
f. industrial ☐ g. residential ☒  
h. other: \_\_\_\_\_
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:  
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Carved exterior trim

**SIGNIFICANCE**

19. DATE OF INITIAL CONSTRUCTION: 1890's

ARCHITECT: \_\_\_\_\_

BUILDER: \_\_\_\_\_

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME:



# BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION  
NEW YORK STATE PARKS AND RECREATION  
ALBANY, NEW YORK (518) 474-0479

## FOR OFFICE USE ONLY

UNIQUE SITE NO. \_\_\_\_\_  
QUAD \_\_\_\_\_  
SERIES \_\_\_\_\_  
NEG. NO. \_\_\_\_\_

YOUR NAME: EUGENIA R. BRADLEY DATE: 6/75  
YOUR ADDRESS: RD 2, Box 405  
RED HOOK, N.Y. 12571 TELEPHONE: 914-758-4351  
ORGANIZATION (if any): \_\_\_\_\_

\*\*\*\*\*

### IDENTIFICATION

1. BUILDING NAME(S): \_\_\_\_\_
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: WEST MARKET ST, RED HOOK
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: DONALD E. NORTON ADDRESS: 14 THOMPSON ST, RED HOOK
6. USE: Original: HARDWARE STORE Present: 4 APT HOUSE
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐  
Interior accessible: Explain \_\_\_\_\_

### DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☒ d. board and batten ☐  
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: \_\_\_\_\_
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐  
(if known) b. wood frame with light members ☐  
c. masonry load bearing walls ☒  
d. metal (explain) \_\_\_\_\_  
e. other \_\_\_\_\_
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? \_\_\_\_\_  
c. list major alterations and dates (if known):  
Removal of front porch.

12. PHOTO:

13. MAP:

