

LANDMARKS

Dutchess County Landmarks Association, Inc.
P.O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook, N.Y. Code No. _____

1. BUILDING NAME Home-Dwelling

2. VILLAGE or HAMLET Red Hook, N.Y.

3. STREET or ROAD 24 Phillips

4. OWNERSHIP: Public ☐ Private ☒

5a. PRESENT OWNER George D. Harrison

Mailing Address 24 Phillips St.

Deed Recorded: Liber _____ Page _____

5b. PRESENT OCCUPANT George D. Harrison


Mailing Address 24 Phillips St.
Red Hook, N.Y. 12571

5c. FORMER OWNERS

Name	Dates of Ownership
<u>M.R. Craft</u>	<u>1858</u>
<u>C. Heyne & wife</u>	<u>1919</u>

13. MAP

North



6. USES

Present _____

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard ☒ stone _____ brick _____
board and batten _____ shingles ☒ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) ☒ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good ☒ fair _____ deteriorated _____

11. INTEGRITY: Original site ☒ If moved, when and from where _____
List major alterations and dates: _____

metal roof removed and shingles used for replacement 1972

12. ROOF: a. gable _____ saltbox _____ gambrel ☒ hip _____ mansard _____ other _____
b. wood shingles _____ asphalt shingles ☒ slate _____ metal _____ other _____

14. THREATS TO BUILDING: none known ☒ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 103 ft x 162 ft acreage 3/4 barn _____
carriage house _____ garage ☒ privy _____ shed ☒ greenhouse _____ shop _____ gardens ☒
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land ☒ woodland _____ scattered buildings _____ residential ☒
densely built-up _____ commercial _____ industrial _____ other _____

(over)

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date 1958 Architect not known Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of
early photographs: _____

Inventory by

Christina Shook.
53 Garden St.
Red Hook, N.Y.

Date

5/17/75

Tel.

758-4036

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: George D. Harrison DATE: 5/17/75

YOUR ADDRESS: 24 Phillips St. Red Hook, N.Y. TELEPHONE: 758-5341


ORGANIZATION (if any): Red Hook Fire Dept. (Police)

IDENTIFICATION

1. BUILDING NAME(S): Dwelling
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: 24 Phillips St. N.Y.S.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: George D. Harrison ADDRESS: 24 Phillips St. Red Hook, N.Y. 12571
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☒ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): Shingles used to cover Clapboard 472
metal Roof removed and shingles used to replace same
12. PHOTO: _____
13. MAP: replace same



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☒ *vegetable*
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: 1858
- ARCHITECT: _____
- BUILDER: _____
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE: *Nothing*

21. SOURCES:

22. THEME: