

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook 4.4 Code No. _____

1. BUILDING NAME former

2. VILLAGE or HAMLET Red Hook

3. STREET or ROAD St. John St.

4. OWNERSHIP: Public _____ Private _____

5a. PRESENT OWNER _____

Mailing Address _____

Deed Recorded: Liber _____ Page _____

5b. PRESENT OCCUPANT David Moulton

Mailing Address _____

5c. FORMER OWNERS
Name _____

Dates of Ownership _____

Deed Recorded
Liber _____ Page _____

6. USES
Present _____

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard _____ stone _____ brick _____
board and batten _____ shingles _____ stucco ☒ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) ☒
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls ☒
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good _____ fair ☒ deteriorated _____

11. INTEGRITY: Original site yes If moved, when and from where _____
List major alterations and dates: big - 200

12. ROOF: a. gable ☒ saltbox _____ gambrel ☒ hip small mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles ☒ slate _____ metal _____ other _____


14. THREATS TO BUILDING: none known _____ zoning ☒ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 1.4 acreage _____ barn _____
carriage house _____ garage 4 privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings ☒ residential _____
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

Present lg - 4 car garage was a cooperage (when apple barrels were made in the 1800's)

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of early photographs: _____

Inventory by _____
Address _____

Date _____
Tel. _____

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: RUTH ARCHER DATE: 7-15-75

YOUR ADDRESS: 260 TURKEY HILL RD. Red Hook TELEPHONE: 914-758-8339

ORGANIZATION (if any): LANDMARKS

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: RED Hook
3. STREET LOCATION: ST. JOHN ST.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: DAVID MOWLTON ADDRESS: Red Hook, N.Y.
6. USE: Original: Cooperage Present: Sound Studio
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☐ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☒ other: _____
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☐
b. wood frame with light members ☐
c. masonry load bearing walls ☒
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☐ c. fair ☒ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



4. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
5. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒ 4-car
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
6. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☒
f. industrial ☐ g. residential ☒
h. other: _____
7. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

8. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

The present 4 car garage was originally
a cooperage where they made apple barrels
in the 1800's.

SIGNIFICANCE

9. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

10. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

11. SOURCES: