

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook Code No. _____

1. BUILDING NAME _____

2. VILLAGE or HAMLET Red Hook

3. STREET or ROAD Fisk

4. OWNERSHIP: Public _____ Private ☒
5a. PRESENT OWNER R.A. STREIB

Mailing Address 24 FISK ST Red Hook N.Y.

Deed Recorded: Liber 1220 Page 677
5b. PRESENT OCCUPANT same

Mailing Address _____

5c. FORMER OWNERS

Name
IRMA DYK E man
ROY WINE

Dates of Ownership
11/9/62 - 4/14/67
2/1/54

Deed Recorded
Liber Page

851 254

Nellie Stickle
ELVIN F STICKLE

5/31/1906
5/8/1906

346 224
346 149

Philip Fraleigh
Hoffman, Horace A. W

12/11/1889
4/15/1887

247 72
230 266

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard ☒ stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other aluminum

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) ☒
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent _____ good ☒ fair _____ deteriorated _____

11. INTEGRITY: Original site ☒ If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable ☒ saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles ☒ slate _____ metal _____ other _____


14. THREATS TO BUILDING: none known ☒ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 1/2 acreage _____ barn ☒
carriage house _____ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land ☒ woodland ☒ scattered buildings _____ residential ☒
densely built-up _____ commercial _____ industrial ☒ other _____

13. MAP

North



Negative BW 40097
Picture # 11

1" = 1/4 mi

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. laid up basement wall - 3 sections opening into each other by wooden doors.
manner on roof - simple cooling system
wainscoting dado in kitchen & den room

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

laid up stone walls
square hand made nails

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

Deeds Transferring title from Fisk to Hoffman and Fraleigh indicate a large barn

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas BIERS ATLAS School District No. _____

1876 Atlas _____ School District No. _____

F. RABBITT - VIO CLERK RA

Location of
early photographs: _____

Inventory by

Barbara C Street

Address

24 Fisk St

Pal Hook NY

Date

May 1975

Tel.

914-78-8651

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Barbara C Streib DATE: _____

YOUR ADDRESS: 24 FISK ST Red Hook TELEPHONE: (914) 718-8651

ORGANIZATION (if any): _____

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: 24 FISK ST
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Richard + Barbara Streib ADDRESS: 24 FISK ST
6. USE: Original: residence Present: residence
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☐ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other aluminum siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☒ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

*Dado of wainscoting in kitchen & dining room
laid-up stone basement - 3 sections connect-
ed by wooden doors*

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES:

22. THEME: