

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY RED HOOK Code No. _____

1. BUILDING NAME _____

2. VILLAGE or HAMLET RED HOOK

3. STREET or ROAD 5355 WEST MARKET ST.

4. OWNERSHIP: Public _____ Private X
5a. PRESENT OWNER HERBERT EUGENE SIMMONS

Mailing Address 5355 WEST MARKET ST.
RED HOOK N.Y. 12571

11/20/64 Deed Recorded: Liber 1160 Page 152

5b. PRESENT OCCUPANT OWNER

Mailing Address SAME AS ABOVE

5c. FORMER OWNERS

Name

Dates of Ownership

Deed Recorded
Liber Page

6. USES

Present

M. STICKLES

PRIVATE RES.

Roy Scism

11/20 1964

" "

H. EUGENE SIMMONS

1964-1975

1160 152

" "

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes X No _____
Interior accessible: Explain _____

8. BUILDING MATERIAL: clapboard X stone _____ brick _____
board and batten _____ shingles _____ stucco _____ other _____

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) _____
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls X
d. metal (explain) _____ e. other _____

10. CONDITION: excellent X good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site X If moved, when and from where _____
List major alterations and dates: _____

12. ROOF: a. gable X saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate X metal _____ other _____


14. THREATS TO BUILDING: none known X zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot _____ acreage 1/4 barn _____
carriage house _____ garage X privy _____ shed _____ greenhouse _____ shop _____ gardens flowers
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential X
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North



17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

BLACK MARBLE FIREPLACE
PORCHES

COVERED
WELL (WORKING WITH
BUCKET)

19. INITIAL CONSTRUCTION:

Date 1900's (early) Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of
early photographs: _____

Inventory by

Address

EUGENIA R. BRADLEY
RD 2 Box 405
RED HOOK, N.Y.

Date

Tel.

6/75
758-4351

BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: BRADLEY, EUGENIA R. DATE: 6/75
YOUR ADDRESS: RD 2, Box 405 TELEPHONE: 914-758-4351
RED HOOK, N.Y.
ORGANIZATION (if any): LANDMARKS

IDENTIFICATION


1. BUILDING NAME(S): _____
2. COUNTY: DUTCHESS TOWN/CITY: _____ VILLAGE: RED HOOK
3. STREET LOCATION: 53-55 WEST MARKET ST.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: H. EUGENE SIMMONS ADDRESS: 53-55 W. MARKET ST.
6. USE: Original: _____ Present: _____
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☐
(if known) b. wood frame with light members ☐
c. masonry load bearing walls ☒
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known): _____

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:

- a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐ flower
i. landscape features: _____
j. other: _____

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):

- a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

BLACK MARBLE FIRE PLACE

PORCHES

CHAIR RAILS

COVERED WELL

(WORKING WITH BUCK)

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: Early 1900's

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

21. SOURCES: