

LANDMARKS

Dutchess County Landmarks Association, Inc.
P. O. Box 944, Poughkeepsie, New York 12602

BUILDING - STRUCTURE INVENTORY FORM

TOWNSHIP or CITY Red Hook Code No. _____

1. BUILDING NAME _____

2. VILLAGE or HAMLET _____

3. STREET or ROAD 8 Thompson St.

4. OWNERSHIP: Public _____ Private X

5a. PRESENT OWNER Mr. + Mrs. Daniel Griffin

Mailing Address 8 Thompson St.
Red Hook

Deed Recorded: Liber 1073 Page 301

5b. PRESENT OCCUPANT Mr. + Mrs. Daniel Griffin

Mailing Address _____

5c. FORMER OWNERS

Name

Dates of Ownership

Deed Recorded
Liber Page

6. USES
Present

Frances M. Conley

1943-62

316 235

house

Mary E. Cronan

1901-1943

(interstate)

7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ✓ No _____
Interior accessible: Explain ✓

8. BUILDING MATERIAL: clapboard siding stone Foundation brick _____
board and batten _____ shingles _____ stucco _____ other aluminum

9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints (post and beam) ✓
b. wood frame with light members (balloon frame) _____ c. masonry load bearing walls _____
d. metal (explain) _____ e. other _____

10. CONDITION: excellent ✓ good _____ fair _____ deteriorated _____

11. INTEGRITY: Original site ✓ If moved, when and from where _____
List major alterations and dates:

addition living room - 1962

porch + bedroom 1967, aluminum siding 1975

12. ROOF: a. gable ✓ saltbox _____ gambrel _____ hip _____ mansard _____ other _____ dormers _____
b. wood shingles _____ asphalt shingles _____ slate _____ metal _____ other _____

14. THREATS TO BUILDING: none known _____ zoning _____ roads _____ developers _____ deterioration _____
other _____

15. RELATED OUTBUILDINGS AND PROPERTY: size of lot 150 x 110 acreage 3 barn _____
carriage house _____ garage _____ privy _____ shed _____ greenhouse _____ shop _____ gardens _____
landscape features _____ other _____

16. SURROUNDINGS OF BUILDING: open land _____ woodland _____ scattered buildings _____ residential ✓
densely built-up _____ commercial _____ industrial _____ other _____

13. MAP

North

Route 199



Thompson St.

1073
296

(over)

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

If structure is in an historic district, name district. _____

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE: (Include interior features if known)

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date 1962 - 1975 Architect completely Builder BB Bradley, Wilson, Lawson

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolutionary _____ Federal _____ Greek Revival _____ Victorian ☒ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

21. SOURCES:

Maps: (List name of owner as shown on map and School District where applicable)

1850 Dutchess Co. _____ 1858 Dutchess Co. _____

1867 Atlas _____ School District No. _____

1876 Atlas _____ School District No. _____

Location of early photographs: at the house -

Inventory by

Address

Mrs. William Walsh
17 Maryland Rd
Red Hook, N.Y. 12571

Date

Tel.

June 1975
PLB-3291



BUILDING-STRUCTURE INVENTORY FORM

NEW YORK STATE HISTORIC TRUST
OFFICE OF PARKS AND RECREATION
ALBANY, NEW YORK (518) 457-3753

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: MRS. Wm. J. WALSH DATE: June 1975

YOUR ADDRESS: 17 MAIZELAND RD., RED HOOK TELEPHONE: 914-758-3291

ORGANIZATION (if any): LANDMARKS

IDENTIFICATION

1. BUILDING NAME(S): _____
2. COUNTY: Dutchess TOWN/CITY: _____ VILLAGE: Red Hook
3. STREET LOCATION: 8 Thompson St.
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Mr. & Mrs. DANIEL GRIFFIN ADDRESS: 8 Thompson St.
6. USE: Original: _____ Present: Residential
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: ☒ Explain _____

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone foundation c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: aluminum siding
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☒ b. good ☐ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known):
addition to living room 1962
porch & bedroom 1967
aluminum siding 1975
12. PHOTO: _____
13. MAP: _____

14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☐ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____
17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:
(Indicate if building or structure is in an historic district)
18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

over 100 years old.

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____
ARCHITECT: _____
BUILDER: _____
20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:
21. SOURCES: