

Dutchess County Landmarks Association, Inc.

P. O. Box 944, Poughkeepsie, N. Y. 12602


BUILDING-STRUCTURE INVENTORY FORM

TOWNSHIP
OR CITY

Red Hook

Code
No.

13. MAP:



1. BUILDING NAME(S) Red Hook Farmers' Co-op
2. VILLAGE OR HAMLET Red Hook
3. STREET OR ROAD Depot St
4. OWNERSHIP: public _____ private ☒
- 5a. PRESENT OWNER Stockholders
- 5b. PRESENT OCCUPANT _____ ADDRESS _____

Negative BW 40097
Picture #8

6. OTHER OWNERS
Names

Dates of
Ownership

Dutchess County Deed Record
Liber No. _____ Page _____

D. W. WILBER

5/8/1900

307

155

8. USE:

Original Creamery

Present Storage for Farmers' Co-op

7. ACCESSIBILITY TO PUBLIC:

Exterior visible from public road, yes ☒ no _____

Interior accessible: Explain

No-Retail Store Storage

8. BUILDING MATERIAL: clapboard ☒ stone _____ brick _____

board and batten _____ shingles _____ stucco _____

other Glazed tile - Concrete

9. STRUCTURAL SYSTEM:

a. wood frame with interlocking joints (post and beam) ☒

b. wood frame with light members (balloon framing) _____

c. masonry load bearing walls ☒ d. metal (explain) _____

d. other Glazed tile - floor + walls

10. CONDITION:

excellent _____

good ☒

Fair _____

deteriorated _____

11. LOCATION:

original site ☒ Moved _____ If moved, when and from where _____

12. ROOF:

a. gable ☒ saltbox _____ gambrel _____ hip _____ mansard _____ other _____

b. wood shingles _____ asphalt shingles ☒ slate _____ metal _____ other _____

14. THREATS TO BUILDING:

none known ☒

zoning _____

roads _____

developers _____

deterioration _____

other _____

15. RELATED OUTBUILDINGS AND PROPERTY:

barn _____ carriage house _____ garage _____ privy _____ shed _____ greenhouse _____

shop _____ gardens _____ landscape features natural other _____

size of lot 2 acreage 2 acres

16. SURROUNDINGS OF THE BUILDING:

open land ☒

woodland _____

scattered buildings _____

densely built-up _____

commercial _____

industrial ☒

residential _____

other _____

(over)

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(If structure is in an historic district, name district. _____)

The surroundings enhance the building

18. OTHER NOTABLE FEATURES OF THE BUILDING AND SITE:

(Include interior features if known) North end was a concrete room for storing ice obtained from Hudson River and local lakes - packed in sawdust for summer. Electrical Refrigeration installed in late 1920's. Tiled room was used for washing creamery equipment. The railroad tracks bisected the station and the creamery

19. INITIAL CONSTRUCTION:

Date _____ Architect _____ Builder _____

SIGNIFICANT ALTERATIONS:

Date _____ Architect _____ Builder _____

20. ARCHITECTURE: (Indicate period or style if known)

Pre-Revolution _____ Federal _____ Greek Revival _____ Victorian _____ Other _____

20a. HISTORICAL INFORMATION AND TRADITIONS:

- a. There has been no industrial development in the area and very little residential
- b. No it is not an architectural example
- c. The structure was associated with the Dairy mens League Co-operative, Barden Farm, Railway Express
- d. No
- e. No significance in its relationship to the street, other buildings etc

21. SOURCES:

Maps: (List name of owner as shown on map and School District Number if shown.)

1880 Dutchess Co. _____ 1888 Dutchess Co. _____
 1867 Atlas _____ School District No. _____
 1876 Atlas _____ School District No. _____

Red Hook Advertiser 5/13/1913

Location of early photographs:

Inventory by Barbara C Streib
 Address 24 FISK ST
Red Hook NY

Date May 1971
 Tel. 914-778-8671

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Barbara C. Streib DATE: May 1971

YOUR ADDRESS: 24 Fisk ST, Red Hook TELEPHONE: 914-758-8651


ORGANIZATION (if any): Dut. Co Landmarks Assoc., Inc.

IDENTIFICATION

1. BUILDING NAME(S): Red Hook Farmers' Co-op (1)
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: Depot ST
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Stockholders ADDRESS: _____
6. USE: Original: ~~Freight Station~~ Present: STORE
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain Retail Store

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: _____
9. STRUCTURAL SYSTEM: a. wood frame with interlocking joints ☒
(if known) b. wood frame with light members ☐
c. masonry load bearing walls ☐
d. metal (explain) _____
e. other _____
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? 1921
c. list major alterations and dates (if known): Freight Station moved across Road. Large doors in remaining bldg. were removed & display windows were installed - coal bin became office and cashier's station. ~~Station remains the same.~~
12. PHOTO: _____
13. MAP: _____



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____
15. RELATED OUTBUILDINGS AND PROPERTY:
a. barn ☐ b. carriage house ☐ c. garage ☒
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☒ h. gardens ☐
i. landscape features: _____
j. other: _____
16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):
a. open land ☒ b. woodland ☐
c. scattered buildings ☒
d. densely built-up ☐ e. commercial ☐
f. industrial ☐ g. residential ☒
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

This building contributes little to its surroundings. However, the natural landscaping softens the serviceable appearance of the structure.

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

Interior walls are wooden

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

This building was a passenger and freight stop for the Rhinebeck & Coun. R.R. In 1921 the Farmer's Co-op bought the building, removed the freight doors, placed windows in the openings, replaced the coal bin with an office and cashiers and added a storage area and loading platform on the right end of the building. The Railroad was terminated at this place, the Co-op moved it across the road and used it for a garage.

21. SOURCES:

22. THEME:

BUILDING-STRUCTURE INVENTORY FORM

DIVISION FOR HISTORIC PRESERVATION
NEW YORK STATE PARKS AND RECREATION
ALBANY, NEW YORK (518) 474-0479

FOR OFFICE USE ONLY

UNIQUE SITE NO. _____
QUAD _____
SERIES _____
NEG. NO. _____

YOUR NAME: Barbara C. Streib DATE: May 1975
YOUR ADDRESS: 24 Fisk St - Red Hook TELEPHONE: 78-8651 (914)
ORGANIZATION (if any): Det. Co Landmarks Assoc Inc

IDENTIFICATION


1. BUILDING NAME (S): Red Hook Farmers' Co-op (2)
2. COUNTY: Dutchess TOWN/CITY: Red Hook VILLAGE: Red Hook
3. STREET LOCATION: Depot St
4. OWNERSHIP: a. public ☐ b. private ☒
5. PRESENT OWNER: Stockholders ADDRESS: _____
6. USE: Original: CREAMERY Present: STORAGE For Farmers' Co-op
7. ACCESSIBILITY TO PUBLIC: Exterior visible from public road: Yes ☒ No ☐
Interior accessible: Explain Retail Store Storage

DESCRIPTION

8. BUILDING MATERIAL: a. clapboard ☒ b. stone ☐ c. brick ☐ d. board and batten ☐
e. cobblestone ☐ f. shingles ☐ g. stucco ☐ other: Glazed tile - concrete
9. STRUCTURAL SYSTEM: (if known) a. wood frame with interlocking joints ☒
b. wood frame with light members ☐
c. masonry load bearing walls ☒
d. metal (explain) _____
e. other: CERAMIC tile floor and walls
10. CONDITION: a. excellent ☐ b. good ☒ c. fair ☐ d. deteriorated ☐
11. INTEGRITY: a. original site ☒ b. moved ☐ if so, when? _____
c. list major alterations and dates (if known):
none

12. PHOTO:

13. MAP:



14. THREATS TO BUILDING: a. none known ☒ b. zoning ☐ c. roads ☐
d. developers ☐ e. deterioration ☐
f. other: _____

15. RELATED OUTBUILDINGS AND PROPERTY:

- a. barn ☐ b. carriage house ☐ c. garage ☐
d. privy ☐ e. shed ☐ f. greenhouse ☐
g. shop ☐ h. gardens ☐
i. landscape features: _____
j. other: Farm-Retail store

16. SURROUNDINGS OF THE BUILDING (check more than one if necessary):

- a. open land ☒ b. woodland ☐
c. scattered buildings ☐
d. densely built-up ☐ e. commercial ☐
f. industrial ☒ g. residential ☐
h. other: _____

17. INTERRELATIONSHIP OF BUILDING AND SURROUNDINGS:

(Indicate if building or structure is in an historic district)

Surroundings enhance this building

18. OTHER NOTABLE FEATURES OF BUILDING AND SITE (including interior features if known):

North end of building was a concrete ice storage room. Until electrical refrigeration was installed in the late 1920's. The tiled room was used for washing creamery equipment

SIGNIFICANCE

19. DATE OF INITIAL CONSTRUCTION: _____

ARCHITECT: _____

BUILDER: _____

20. HISTORICAL AND ARCHITECTURAL IMPORTANCE:

The structure was associated with the Dairymen's League Co-operative Garden Farms, Railway Express

21. SOURCES: _____

22. THEME: _____